

ANNEX V - FOD PREVENTION ORDERS

1. FOD Prevention Officer. The RAF Halton FOD Prevention Officer is the AFM and is contactable as follows:

a. Mil: 95237 6799

b. Tel: 0777 152 2083

2. FOD Prevention Officer TORs. The FOD Prevention Officer's TORs include a requirement to log all reported FOD incidents at RAF Halton. Incidents are investigated in accordance with RA 1400 and SEMS (AP8000) Lft 8103 in collaboration with the RAF Halton SFSO. The FOD Prevention Officer also produces a report to the quarterly RAF Halton Flight Safety meetings.

3. FOD Awareness. All personnel posted to RAF Halton are given a FOD Awareness Briefing as part of the monthly Station Arrivals Brief, including details of how to report FOD incidents.

4. Liaison with Airfield Organisations. The location of Supply at the Airfield requires close liaison between the FODPO and nominated Supply FOD Reps to reduce the amount of FOD adjacent to the airfield.

5. Briefing of Contractors. All contractors working at RAF Halton are given a "4Cs" Brief before being allowed to commence work. The 4Cs Brief includes a section on the importance of FOD Prevention, and methods of reporting any incidents. If Contractors need to work Airside, they will be given an Additional Work in Progress brief, which includes areas permitted, areas out of bounds and further FOD prevention measures.